
# **Small and Amplifier Built-in type**

## Small emitter/receiver synchronizing type

#### Features

- Small size: W12×H16×D30mm
- Minimizing malfunction by extraneous light by synchronizing emitter and receiver
- Reverse power polarity and overcurrent protection circuit
- Fast response speed : Max. 1ms





### Specifications

Model		Standard type	Side sensing type	
		BY500-TDT	BYS500-TDT	
Sensing type		Through-beam		7
Sensing distance		500mm		
Sensing target		Opaque materials of Min. ø5mm		Ī
Response time		Max. 1ms		
Power supply		12-24VDC ±10%(Ripple P-P : Max. 10%)		
Current consumption		Max. 30mA		
Light source		Infrared LED(940nm)		
Operation mode		Dark ON		
Control output		NPN open collector output  ■ Load voltage : 30VDC ■ Load current : Max. 100mA ■ Residual voltage : Max. 1V		
Protection circuit		Reverse polarity protection, output short-circuit protection		
Indicator		Operation indicator : red LED		
Insulation resistance		Min. 20MΩ(at 500VDC megger)		
Noise resistance		±240V the square wave noise(pulse width : 1μs) by the noise simulator		
Dielectric strength		1,000VAC 50/60Hz for 1minute		
Vibration		1.5mm amplitude or 300m/s <sup>2</sup> at frequency of 10 to 55Hz(for 1 min.) in each of X, Y, Z directions for 2 hour		
Shock		500m/s²(approx. 50G) in each of X, Y, Z directions for 3 times		
Environ- ment	Ambient illumination	Sunlight: Max. 11,0001x Incandescent lamp: Max. 3,000 lx (Receiving illumination)		
	Ambient temperature	-10 to 60°C, storage : -25 to 70°C		
	Ambient humidity	35 to 85%RH, storage : 35 to 85%RH		
Protection		IP50(IEC standard)		
Material		Case : ABS, Sensing part : Acrylic		
Cable		ø4, 4-wire, Length : 2m (Emitter of through-beam type: ø4mm, 3-wire, Length: 2m) (AWG22, Core diameter: 0.08mm, Nunber of cores: 60, Insulator out diameter: ø1.25)		
Accessory		Mounting bracket, Bolts/Nuts		
Unit weight		Approx. 150g		

XThe temperature or humidity mentioned in Environment indicates a non freezing or condensation environment.

(A)
Photo
electric
sensor

(B)
Fiber
optic
sensor

(C)
Door/Area
sensor

(D)
Proximity
sensor

(E)
Pressure
sensor

(F)
Rotary
encoder

(H) Temp. controller

Power controller

(K)

(M) Tacho/ Speed/ Pulse meter

Speed/ Pulse meter

(N)
Display unit

> O) ensor ontroller

(P) Switching mode power supply

Stepper motor& Driver&Controller

(R) Graphic/ Logic panel


(S) Field network device


(T) Software

(U) Other


Autonics A-25

#### Feature data






### ■ Control output diagram




## Operation mode



- XIf the control output terminal is short-circuited or overcurrent condition exists, the control output turns OFF due to protection circuit.
- ※Please supply the power to the brown and the blue wires of the emitter and Synchronous wire(white) of the receiver must be connected with that of the emitter.

#### Connections




- XThe power of the emitter and the receiver must be supplied from same power line.
- XSynchronous wire(white) of the receiver must be connected with that of the emitter, or it may cause malfunction.

A-26 Autonics

# **Small and Amplifier Built-in type**

■ Dimensions (unit: mm)







• BYS500-TDT

9

5






12


M3.5 Bolt


Optical axis



# ■ Mounting and sensitivity adjustment

- 1. Supply the power to the sensor, after installing the emitter and the receiver facing each other.
- Set the receiver in the middle of position where the operation indicator turns ON adjusting the receiver to the right and the left or up and down.
- 3. Fix both units tightly after checking that the unit detects the target.
- ※If a sensing target is translucent body or smaller than ø5mm, it might not be detected because the target allows too much light to pass.





(A) Photo electric sensor

(B) Fiber optic sensor

> (C) Door/Area sensor

(D) Proximity

(E) Pressure

(F) Rotary

(G)

Socket

Temp. controller

(I) SSR/ Power controller

Counter

(K) Timer

> Panel neter

(M) Tacho/ Speed/ Pulse meter

nit

O) Sensor controller

(P) Switching mode power supply

(Q) Stepper motor& Driver&Controlle

(R) Graphic/ Logic panel

(S) Field network device

T)

Software

(U) Other

Autonics A-2